NOFORM

BYE-1987_62 cy 1/of 1/

23 JUL 1962

MEMORANDUM FOR: Chief, Office of Special Activities/DDR

ATTENTION

: Mr. Dave Sharp

SUBJECT

: Technical Evaluation of Mission 3085

- 1. The HEPC evaluation of this mission was made from original recordings.
 - 2. Performance of Recording Equipment:

All recording apparatus functioned properly during the reconnaissance.

- 3. Performance of Receiving Equipment:
- a. P-band. Coherent analysis of the P-band data was extremely difficult because of intense vehicle associated 400 cps interference.
- b. L-band. The usual interference related to camera activity was noted.
 - c. S-band. This receiver performed properly.

d. X-band. Satisfactory operation of the receiver prevailed throughout the flight.

25**X**1

Acting Chief
Elint & Special Projects Division

25 YEAR RE-REVIEW

SELLIL NOFORN

GROUP 1
Excluded from automatic downgrading and declassification

Sanitized Copy Approved for Release 2010/05/25 : CIA-RDP89B00569R000700060052-5 '987-1

SUBJECT: Technical Evaluation of Mission 3085

Distribution:

Orig & 1 - Addressee

1 - OSA/Intel/DDR

1 - SPB/OSA/DDR

2 - ESPD/SI

2 - DPB/ESPD/SI

OSI/ESPD/DPB:JHPearch:ldn:7141 (20 July 1962)